



Product Safety Recall



LV1980



LV1981



LV1992



LV1993



LV1994



LV1995



LV1996



LV1998

Powercon Jump Starters

LV1980, LV1981, LV1992, LV1993, LV1994, LV1995, LV1996 & LV1998

AAEW and Low Voltage are issuing a product recall on its Powercon Jump Starters (LV1980, LV1981, LV1992, LV1993, LV1994, LV1995, LV1996 and LV1998) sold in Australia and New Zealand since March 2015 through its own Branch network and various retailers and distributors.

What are the defects?

AAEW have identified possible situations where use or potential misuse can lead to product failure, resulting in overheating, which can lead to the product combusting.

What are the hazards?

The prime cause of the issue is: products may overheat and combust including where units are left connected to vehicle batteries for extended periods after a vehicle is started, resulting in property damage and or serious personal injury.

What should consumers do?

Consumers should immediately stop using the product and contact the place of purchase for a full refund.

Contact details: Contact JAS Oceania by phoning 1800 577 378 (Monday to Friday, 8.30am-5.30pm AEST), emailing powerconrecall@jasoceania.com.au or going to www.jasoceania.com.au

**See productsafety.gov.au for
Australian product recall information**